Roadway Segment Analysis

Table 4.9 shows the level of service for roadway segments along the Ramon Road corridor The volume to capacity ratios are calculated using micro-simulation green times and number of lanes at ends of each link. See **Appendix E** for ADT calculations.

Table 4.9 Existing Capacity Analysis

Ramon Road	ADT	CAPACITY	V/C	LOS
West of Landau	43,473	68,550	0.634	В
West of Cathedral Canyon	38,659	70,272	0.550	A
West of Date Palm	32,538	97,056	0.335	A
East of Date Palm	29,682	59,904	0.495	A
West of Da Vall	27,060	81,216	0.333	A
East of Da Vall	26,773	73,440	0.365	A
Landau Blvd				
North of Ramon	18,495	28,224	0.655	В
Cathedral				
Canyon/Maravilla				
North of Ramon	4,532	22,464	0.202	A
South of Ramon	16,053	33,264	0.483	A
Date Palm				
North of Ramon	25,532	43,488	0.587	A
South of Ramon	26,413	43,488	0.607	В
Da Vall				
North of Ramon	10,187	21,312	0.478	A
South of Ramon	14,189	26,496	0.536	A

Roadway Segment Analysis

Table 7.5 shows the estimated level of service for roadway segments along the Ramon Road corridor. The volume to capacity ratios are calculated using micro-simulation green times and number of lanes at ends of each link. See **Appendix E** for ADT calculations.

Ramon Road ADT **CAPACITY** V/C LOS West of Landau 63,700 0.920 E 69,211 West of Cathedral Canyon 49,700 | 70,560 0.704 C West of Date Palm 53,300 96,624 0.552 A 0.799 C East of Date Palm 49,267 61,632 52,033 88,416 0.589 West of Da Vall A East of Da Vall 66,600 70,272 0.948 Ε Landau Blvd \mathbf{C} 21,269 27,792 0.765 North of Ramon Cathedral Canyon/Maravilla North of Ramon 5,212 23,616 0.221 A 33,264 0.555 South of Ramon 18,461 Α **Date Palm** North of Ramon 33,933 | 44,208 0.768 C South of Ramon 32,533 | 43,488 0.748 C Da Vall North of Ramon 29,433 24,912 F 1.181 South of Ramon 21,000 30,240 0.694 C

Table 7.5 Long Term Capacity Analysis

7.3 Summary of Long Term Conditions

Using existing lane configurations, the PM peak period experiences frequent congestion. Existing road segment widths do not adequately support future volumes along Ramon Road west of Landau and east of Da Vall. All other road segments provide adequate capacity such that vehicles may maintain their desired speed. **Table 7.6** summarizes intersection conditions.

IntersectionIssuesRamon and LandauSignificant eastbound queuing on the bridge.Ramon and Cathedral CanyonSignificant queuing in all approaches. West and eastbound queuing blocks cross streets such as Alvera or Roundup.Ramon and Date PalmAll single lane left turn bays spillover to frequently block through lanes.Ramon and Cathedral VillageEastbound frequently backs up to block Date Palm.Ramon and Da VallCapacity of single north and south through lanes is exceeded.Major queuing occurs if green is extended to serve these vehicles.

Table 7.6 Long Term Intersection Summary



ADVANTEC Consulting Engineers